
20
(A)
44
PDMS peeled away from master
20
(B)
26
26
26
PDMS exposed to solution of $HS(CH_2)_{15}CH_3$
20
(C)
28
Stamping transfers thiol
32 35
37 36 37 36 37 36 37
(D)
34
100 μm
(F)
Surface exposed to solution of $HS(CH_2)_{11}(OCH_2CH_2)_6OH$
38 36
(E)
SEM
Surface exposed to laminin
39
(G)
SEM
(H)
Cells seeded on surface
40
(I)
SEM
(J)

FIG. 1